


SCREW TRAP SAFETY FEATURES

Below is a schematic of the required safety features that all screw traps MUST have in place before they are to be operated. Inspect traps frequently for these features. If any of these features are missing or damaged –STOP THE TRAP AND CALL YOUR SUPERVISOR.



- All traps must have a throw rope and life-ring on deck at all times.
- Warning signs must be present on the trap

Important Notes:

- Hand rails must have a top and bottom rail and port side (left) rail must have **solid plate near pinch point** at bottom (see photo)
- PFD must be worn on traps



Photo of Cone Guard and Shaft Guard (modified minnow trap).



Photo showing proper hand rails. Note metal plate at pinch point on port side and proper signage. All required.